

质量管理体系认证证书

证书编号: ISC-Q-2024-4426-R 兹证明 甘肃铸匠机械制造有限公司

统一社会信用代码: 91620403MA71UMDH6U

注册地址: 甘肃省白银市平川区电力路 1 号 1 幢 3 层(限于行政办公和通讯联络) 邮编: 730900 **经营地址:** 甘肃省白银市平川区电力路 1 号(容和集团厂区内) 邮编: 730900

管理体系符合

GB/T19001-2016/ISO9001:2015 标准要求 **认证范围:**

矿山机械设备配件的制造

发证日期: 2024 年 09 月 10 日 有效期至: 2027 年 09 月 09 日







中国认可 国际互认 管理体系 MANAGE

MANAGEMENT SYSTEM CNAS C272-M 认证机构:





此证书信息可在国家认证认可监督管理委员会官方网站(www.cnca.gov.cn)上查询 此证书信息可在本认证机构官方网站(www.china-isc.org.cn)上查询 此证书的有效期以证书二维码扫描结果为准。

注: 获证组织必须定期接受监督审核,并与监督审核(查)合格通知书一并使用。

地址:北京市朝阳区北三环东路8号1幢-3至26层101内8层810房间 电话: (+86 10) 8225 2376 www.china-isc.org.cn



Quality Management System Certificate

Registration No. ISC-Q-2024-4426-R

This is to certify that

Gansu Zhujiang Machinery Manufacturing Co., Ltd

The social credit code: 91620403MA71UMDH6U

Registered Address: 3rd Floor, Building 1, No. 1 Dianli Road, Pingchuan District, Baiyin City, Gansu Province

(limited to administrative offices and communication)

Audit Address: 3rd Floor, Building 1, No. 1 Dianli Road, Pingchuan District, Baiyin City, Gansu Province (limited

to administrative offices and $\operatorname{communication}$)

Which is in conformity with

GB/T19001-2016/IS09001:2015

This certificate covers the following scope of

Manufacturing of mining machinery equipment accessories

Issue Date: 2024-09-10 Expiration Date: 2027-09-09



Issued by:





中国认可 国际互认 管理体系 MANAGEMENT SYSTEM CNAS C272-M

Beijing International Standard united Certification Co.,Ltd.



The validity of this certificate is subject to the scanning result of the two—dimensional code of the certificate

This certificate information can be inquired on the official website of the certification authority (www.china-isc. Org. CN)

This certificate information can be inquired on the official website of China Certification and Accreditation Administration (www.cnca. Gov.cn)

Note: the certified organization must accept the supervision and sudit regularly and use it together with the supervision and audit (inspection) qualification notice.