



环境管理体系认证证书

证书编号：19725E00014R101

兹证明

沧州金特五金制造有限公司

统一社会信用代码：91130927559064937B

注册地址：南皮县冯家口镇后上桥村

邮编：061500

经营地址：南皮县冯家口镇后上桥村

邮编：061500

管理体系符合

GB/T 24001-2016/ISO 14001:2015 《环境管理体系 要求及使用指南》标准要求
认证范围：

五金冲压件（含汽车零件）的加工所涉及场所的相关环境管理活动

首次发证日期：2023年02月28日

本次发证日期：2025年12月25日

有效期至：2029年02月27日

签发人



中国认可
国际互认
管理体系
MANAGEMENT SYSTEM
CNAS C272-M

认证机构：北京国标联合认证有限公司



此证书信息可在国家认证认可监督管理委员会官方网站(www.cnca.gov.cn)上查询

此证书信息可在本认证机构官方网站(www.china-isc.org.cn)上查询

此证书的有效性以证书二维码扫描结果为准。

注：获证组织必须定期接受监督审核，并与监督审核（查）合格通知书一并使用。



Environmental Management System Certificate

Registration No. 19725E00014R101

This is to certify that

Cangzhou Jinte Hardware Manufacturing Co., Ltd

The social credit code: 91130927559064937B

Registered Address: Houshangqiao Village, Fengjiakou Town, Nanpi County

Audit Address: Houshangqiao Village, Fengjiakou Town, Nanpi County

Which is in conformity with

GB/T 24001-2016/ISO 14001:2015

Environmental management systems-Requirements with guidance for use

This certificate covers the following scope of

Environmental management activities related to the sites involved in the processing of metal stamping parts
(including automotive parts)

Date of first Issue: 2023-02-28

Issue Date: 2025-12-25

Expiration Date: 2029-02-27

Issued by:



中国认可
国际互认
管理体系
MANAGEMENT SYSTEM
CNAS C272-M

Beijing International Standard United Certification Co.,Ltd.



The validity of this certificate is subject to the scanning result of the two-dimensional code of the certificate.

This certificate information can be inquired on the official website of the certification authority (www.china-isc.org.cn)

This certificate information can be inquired on the official website of China Certification and Accreditation Administration (www.cnca.gov.cn)

Note: the certified organization must accept the supervision and audit regularly and use it together with the supervision and audit (inspection) qualification notice.

Add: Room 809, No. 8 Beisanhuan East Road, Chaoyang District, Beijing.

TEL (+86 10) 8225 2376