



质量管理体系认证证书

证书编号: ISC-Q-2024-4701

兹 证 明

咸阳芮萌涵汽车零部件有限公司

统一社会信用代码: 91610422MAD9NLJW4M

注册地址: 陕西省咸阳市三原县西阳镇西南村西阳工业园区三洋陶瓷厂内西南角1号

邮编: 713800

经营地址: 陕西省咸阳市三原县西阳镇西南村西阳工业园区三洋陶瓷厂内西南角1号

邮编: 713800

管理体系符合

GB/T19001-2016/ISO9001:2015 标准要求

认证范围:

塑料制品生产及加工

本证书自有效期起始日期后的每年度进行监督审核, 监督合格发放《年度监督审核合格通知书》和年度审核报告为准。

本证书信息可在国家认证认可监督管理委员会官方网站(www.cnca.gov.cn)上查询

本证书信息可在认证机构官方网站(www.china-isc.org.cn)上查询

发证日期: 2024 年 11 月 05 日

有效期至: 2027 年 11 月 04 日



证书二维码

签 发 人:

黄文生

认证机构: 北京国标联合认证有限公司





Quality Management System Certificate

Registration No. ISC-Q-2024-4701

This is to certify that

Xianyang Rui Menghan Auto Parts Co., LTD

The social credit code: 91610422MAD9NLJW4M

Registered Address: No.1, Southwest corner, Sanyo Ceramics Factory, Xiyang Industrial Park, Southwest Village, Xiyang Town, Xiyuan County, Sanyuan County, Xianyang City, Shaanxi Province

Audit Address: No.1, Southwest corner, Sanyo Ceramics Factory, Xiyang Industrial Park, Southwest Village, Xiyang Town, Xiyuan County, Sanyuan County, Xianyang City, Shaanxi Province

Which is in conformity with

GB/T19001-2016/ISO9001:2015

This certificate covers the following scope of

Production and processing of plastic products

This certificate shall be subject to supervision and audit every year after the start date of validity, and the annual supervision and audit certificate and annual audit report shall be issued after the supervision is qualified.
The certificate information is available on the CNCA of the official website(www.cnca.gov.cn)
[Search\(www.china-isc.org.cn\)](http://Search(www.china-isc.org.cn))

Issue Date: 2024-11-05

Expiration Date: 2027-11-04



Cert code

Issued by:

Huangyijun

Beijing International Standard United Certification Co.,Ltd.

