



# 质量管理体系认证证书

证书编号：ISC-Q-2024-3518-R

兹证明

陕西西福汽车零部件有限公司

统一社会信用代码：91610131MAB0X9TF9R

注册地址：陕西省西安市高新区草堂工业区正太路北段 999 号

邮编：710000

经营地址：陕西省西安市周至县集贤产业园创业大道 14 号 7 车间

邮编：710000

管理体系符合

GB/T19001-2016/ISO9001:2015 标准要求

认证范围：

机械零部件加工

发证日期：2024 年 02 月 22 日

换发日期：2025 年 09 月 28 日

有效期至：2027 年 02 月 21 日

黄文俊

签发人



中国认可  
国际互认  
管理体系  
MANAGEMENT SYSTEM  
CNAS C272-M

认证机构：北京国标联合认证有限公司



此证书信息可在国家认证认可监督管理委员会官方网站([www.cnca.gov.cn](http://www.cnca.gov.cn))上查询

此证书信息可在本认证机构官方网站([www.china-isc.org.cn](http://www.china-isc.org.cn))上查询

此证书的有效期限以证书二维码扫描结果为准。

注：获证组织必须定期接受监督审核，并与监督审核（查）合格通知书一并使用。

地址：北京市朝阳区北三环东路8号1幢-3至26层101内8层810房间 电话：(+86 10) 8225 2376 [www.china-isc.org.cn](http://www.china-isc.org.cn)



# Quality Management System Certificate

Registration No. ISC-Q-2024-3518-R

This is to certify that

**Shaanxi Xifu Auto Parts Co., Ltd**

The social credit code: 91610131MABOX9TF9R

**Registered Address:** No. 999, North Section of Zhengtai Road, Caotang Industrial Zone, High-tech Zone, Xi' an City, Shaanxi Province

**Audit Address:** Workshop 7, No. 14, Chuangye Avenue, Jixian Industrial Park, Zhouzhi County, Xi' an City, Shaanxi Province

Which is in conformity with  
**GB/T19001-2016/ISO9001:2015**

This certificate covers the following scope of

Processing of mechanical parts and components

Issue Date: 2024-02-22  
Change Date: 2025-02-28  
Expiration Date: 2027-02-21

Issued by:



中国认可  
国际互认  
管理体系  
**MANAGEMENT SYSTEM  
CNAS C272-M**

Beijing International Standard United Certification Co., Ltd.



The validity of this certificate is subject to the scanning result of the two-dimensional code of the certificate  
This certificate information can be inquired on the official website of the certification authority ([www.china-isc.org](http://www.china-isc.org))  
This certificate information can be inquired on the official website of China Certification and Accreditation Administration ([www.cnca.gov.cn](http://www.cnca.gov.cn))  
Note: the certified organization must accept the supervision and audit regularly and use it together with the supervision and audit (inspection) qualification notice.

Add: Room 810, No. 8 Beisanhuan East Road, Chaoyang District, Beijing. TEL ( +86 10) 82252376